

Mary Court

Assessment of fire risks and recommended actions: summary

INSPECTION: JUNE 2021

A SUMMARY OF THE RECOMMENDATIONS SET OUT WITHIN SECTION C TO THE REPORT **ASSESSMENT OF IDENTIFIED RISKS AND RECOMMENDED ACTIONS**

KEY  Action completed or on regular programme.  Work in progress; completion by March 2022.





MUST DO

No actions required.



SHOULD DO

-  Keep records of routine inspections of the common escape routes. The escape routes should be inspected at least monthly.
-  The configuration of the building-wide fire alarm system should be reviewed, giving due consideration to the stay put fire response policy in place.



COULD DO

No actions required.