

# Robertson House

## Assessment of fire risks and recommended actions: summary

INSPECTION: JUNE 2021

A SUMMARY OF THE RECOMMENDATIONS SET OUT WITHIN SECTION C TO THE REPORT **ASSESSMENT OF IDENTIFIED RISKS AND RECOMMENDED ACTIONS**

**KEY**  Action completed or on regular programme.  Work in progress; completion by March 2022.



### MUST DO

No actions required.






### SHOULD DO

No actions required.



### COULD DO

-  Update the Fire Action Notices on display within the common areas.
-  Review fire information provided to residents for more detail.
-  Correct mandatory 'Automatic Fire Door – Keep Clear' signs should be displayed on doors fitted with hold open devices.