

## Mary Court

Assessment of fire risk and recommended actions: summary

Inspection: August 2024 A SUMMARY OF THE RECOMMENDATIONS SET OUT WITHIN SECTION C TO THE REPORT ASSESSMENT OF IDENTIFIED RISKS AND RECOMMENDED ACTION

KEY Action ! Completed or on regular programme

\* Work in progress; completion by March 2025

@ Please call Peter Toulson with any queries

MUST DO	SHOULD DO	COULD DO
No actions required	<ul style="list-style-type: none"><li>* The common areas within a property providing sleeping accommodation should be 'Fire Sterile' &amp; kept clear of storage at all times.</li><li>* All combustible/flammable materials should be removed from the electrical intake cupboard.</li><li>* The door identified should be inspected &amp; eased/adjusted accordingly so that the door adequately self-closes from all angles &amp; sits flush within its frame when closed. Gaps along the bottom edge of any fire door should not exceed 10mm, where this is exceeded the door should be adjusted to compensate for the gap without compromising the allowable 3mm gap on side and top edges of the door.</li><li>* The RHS panel should be upgraded/replaced with approved fire rated materials affording a minimum 30 minutes fire resistance.</li><li>* In accordance with Article 17 of The Regulatory Reform 'Fire Safety' Order 2005 that requires any facilities, equipment or devices provided for Fire Safety purposes must be: 'Subject to a suitable system of maintenance &amp; are maintained in an efficient state, in efficient working order &amp; in good repair.'</li><li>* The breaches in compartmentation identified should be adequately fire stopped.</li><li>* The Emergency Lighting System should be subject to annual maintenance, in accordance with British Standard 5266-8.</li><li>* An inspection of the common areas, incorporating the escape routes &amp; an inspection of any installed fire safety provisions should be performed routinely by a suitably competent person.</li><li>* The property has been designed to support a 'stay put' fire safety strategy, whereby only those directly affected or threatened by are required to evacuate from the premises.</li><li>* Ensure that correct fully completed Fire Action Notices are displayed at the common entrances.</li><li>* In line with the 'Fire Safety Regulations 2022' which applies to all buildings in England that comprise of two or more domestic premises, the responsible person must display Fire Safety Instructions in a conspicuous part of the building.</li><li>* In line with the 'Fire Safety Regulations 2022' which applies to all buildings in England &amp; Section 156 of the 'Building Safety' act; The responsible person must provide Fire Safety Instructions &amp; information to new residents.</li></ul>	<ul style="list-style-type: none"><li>! The enclosures and doors should be upgraded/replaced with approved fire rated materials affording a minimum 30 minutes fire resistance.</li><li>! The areas identified should be upgraded/replaced with approved fire rated materials affording a minimum 30 minutes fire resistance.</li></ul>

Sutton  
Housing  
Society

IF YOU WOULD LIKE TO SEE THE FULL RISK ASSESSMENT, PLEASE CONTACT PETER TOULSON ON 020 8642 1500