

Key performance indications : Property compliance

	Results 2018 / 2019	Results 2019 / 2020	Results 2020 / 2021	Target 2021 / 2022
Completed fire safety risk assessments	100%	100%	100%	100%
Fire risk assessments outstanding	0%	0%	0%	0%
Electrical inspections completed	75%	100%	100%	100%
Homes with valid gas safety certificate	100%	100%	100%	100%
Gas safety checks completed within target	100%	100%	100%	100%
Lift servicing completed	100%	100%	100%	100%
LOLER inspections completed	100%	100%	100%	100%
Compliance with legionella testing / work			100%	100%
Homes meeting Home Standard including DHS	100%	100%	100%	100%